

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo of location From NW corner of the location**

**GORDON ENGINEERING INC**  
**Api # 05-077-08508**  
**Inspection # 675002122**



**Photo #2. Wellhead sign.**

**Photo # 3Tank Battery**

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo #4. Unused, unmarked white chemical containers with no labels.**

**Photo #5 Unused, unmarked white chemical containers with no labels.**

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo #6 . Tank battery sign. 911 not posted on sign,**



**Photo #7 Unused equipment stored on location**

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo #8. Weeds and debris on location**



**Photo #9. Unused equipment. Gas Meter appears to be disconnected. Risers are not marked or locked out tagged out.**

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo #12. Storm Water Erosion moving sediment off the SW entrance of location onto main access road. No BMP's in place**

**Photo #13. Storm water moving onto location from south hillside of location. No BMP's in place**

**GORDON ENGINEERING INC**

**Api # 05-077-08508**

**Inspection # 675002122**



**Photo #10. Storm water Erosion moving sediment along north side of access road**

**Photo #11. Storm water Erosion moving heavy sediment off access road, into ravine.**