


PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Dead weed rubbish between separators and tanks.

PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Slope behind equipment and tanks is sloughing sediment.

PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Slope behind equipment and tanks is sloughing sediment.

PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Slope behind equipment and tanks is sloughing sediment. Sediment washing along tank berm towards the road.

PA 22-34 Production Facility
Location id. # 444624
Inspection # 689702991



Berm is washed out at the front of tank berm.

PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Road and ditch are rutted and damaged from traffic.

PA 22-34 Production Facility

Location id. # 444624

Inspection # 689702991



Road and ditch are rutted and damaged from traffic.