

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 1 Tubing pressure 1900psig



Photo 2 Braden head pressure 0psig

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 3 casing pressure Opsig



Photo 4 Unused equipment, trash and weeds on outer edge of location

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 5 Unused equipment and weeds



Photo 6 sign not posted with correct well name on sign

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 7 Unused equipment trash and weeds in front of pump building



Photo 8 Weeds and unused equipment along fence

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 9 Weeds around electric panels and fence line



Photo 10 Weeds and unused equipment (pump building)

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 11 Unused equipment piping and tanks



Photo 12 Weeds and unused equipment tanks that are in disrepair

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 13 Unused equipment piping and tanks



Photo 14 Unused equipment Pumps and load out equipment

Inspection Photos
Location Name: NGL C2
Location ID: 330267



Photo 15 Unused equipment piping and tanks and weeds



Photo 16 weeds