

Inspection Photos
Operator: BP America
Location/API #: 067-08843
Date: 3-26-2019



Photo 1. View of the project area from the northeastern corner of the working area facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Large kochia (*Kochia scoparia*) debris identified within the outer revegetation areas.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of area along access at stream crossing that is eroding around culverts and is not stabilized. Culverts do not appear sufficiently sized to contain high flows and runoff events.



Photo 5. View of stream crossing where it appears significant sediment was recently discharged. Crossing is not stabilized, and culvert size is not adequate.



Photo 6. Another view of stream crossing showing loose soils and sediment/rock that appear to have recently been washed downstream.