

Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC # 10110

Location ID: 310458

Inspection Document #: 674902709

Weld County, CO

NWSE Section 2 T3N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 1. Photo taken from the access road, facing North. Appears the access road remains to the location and facility. Appears the culvert has failed and water is traversing the access road.



Photo 2. Photo taken from the access road, facing Northwest. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 3. Photo taken from the access road, facing Northeast. See comments from Photo 1.



Photo 4. Photo taken from the access road, facing North. See comments from Photo 1.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 5. Photo taken from the location, facing North. Photo depicts the erosion observed on location.



Photo 6. Photo taken from the location, facing South. See comments from Photo 5.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 7. Photo taken from the location, facing West. Photo depicts the removal of all equipment has been performed. The gravel remains on location and no other reclamation activities were observed.



Photo 8. Photo taken from the location, facing South. See comments from Photo 5.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 9. Photo taken from the location, facing North.
See comments from Photo 7.



Photo 10. Photo taken from the location, facing East.
See comments from Photo 7.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 11. Photo taken from the access road to the facility, facing East. Photo depicts equipment remains on site.



Photo 12. Photo taken from the facility, facing Northeast. See comments from Photo 3.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 310458



Photo 13. Photo taken from the facility, facing East. The gravel remains on the facility and no other reclamation activities were observed.



Photo 14. Photo taken from the facility, facing South. Photo depicts the erosion observed on location.