

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2019

Submitted Date:

04/01/2019

Document Number:

675002112

**FIELD INSPECTION FORM**
 Loc ID 334095 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	All inspection
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259509	WELL	PR	10/16/2003	GW	045-07734	S PARACHUTE TBI 36-23	PR
275947	WELL	PR	03/02/2006	GW	045-10411	TBI 36-10 (PG36)	PR
275948	WELL	PR	05/01/2012	GW	045-10410	TBI 36-11BB (PG360)	PR
275949	WELL	PR	01/01/2019	GW	045-10409	TBI 36-9BB (PG36)	PR
280950	WELL	PR	03/15/2006	GW	045-11383	TBI 36-2 (PG36)	PR

**General Comment:**

Routine FIU General Field Inspection

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	970-285-2615 / 970-301-1319 911 and Nearest Access Posted		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heated Separator	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Separator/dehydrator unit		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 259509 Type: WELL API Number: 045-07734 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 275947 Type: WELL API Number: 045-10411 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 275948 Type: WELL API Number: 045-10410 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 275949 Type: WELL API Number: 045-10409 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in... last production shown 1/19

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 280950 Type: WELL API Number: 045-11383 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
Berms						
Gravel	Pass					
Ditches						
Waddles	Fail	Gravel	Pass			

Comment: Stormwater erosion not being controlled for the location at this time.  
Waddles on south side of location need maintenance  
Hill side on east side of location has erosion and sediment moving off location.  
BMP's not in place or properly maintained.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/02/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401993657	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781945">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781945</a>
675002114	Inspection 675002112 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781939">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4781939</a>