

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/11/2019

Submitted Date:

04/02/2019

Document Number:

694500076

FIELD INSPECTION FORM
 Loc ID 324752 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
James, general		sandridgeenvironmental@san dridgeenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159446	UIC DISPOSAL	AC	08/01/2014	DSPW	-	ECLIPSE SWD	EI
463151	SPILL OR RELEASE	AC	03/22/2019		-	Vaneta 1-32D	EI

General Comment:

On 3/11/2019 COGCC Environmental staff inspected the Vaneta 1-32D (location 324752) and spill number 463151. Weather was 34 degs and overcast, snow, mud and surface water were present. Trucks were actively unloading fluid, as a result, the location was observed from a distance. The area of impact from spill 463151 appears to be the area where the frac tanks were set. Snow covered the area of impact, none of the ground was observable. Spill communication will continue on the Form 19. Please provide information on the use of the frac tanks on FIRR. If tanks are being used on location, please contact COGCC staff Kris Neidel for action required.

Inspected Facilities									
Facility ID:	159446	Type:	UIC	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	463151	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: Tanks have oil staining where they have overflowed.

Corrective Action: remove staining and prevent fluid from overtopping tanks.

Date: 04/04/2019

Reportable: NO

GPS: Lat _____ Long _____

Proximity to Surface Water: 1480

Depth to Ground Water: 20

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401992460	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780923
694500077	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780920