

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 1**



**Pic 2**

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 3**



**Pic 4**



Inspection Photos  
Location Name: Millard #1  
Location ID: 333131



Pic 5



Pic 6

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 7**



**Pic 8**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 9 Appears to have stained soil under new soil.**



**Pic 10**

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 11** Appears to be stained soil covered with new soil.



**Pic 12**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Pic 13 No NFPA Placard on Separator.**



**Pic 14 Inside of separator, leaking pipes appear to still be leaking. New soil appears to be covering stained soil.**