

Inspection Photos

Location Name: APACHE CANYON 35-07

API #: 05-071-09320

Insp. Doc. # 695100451



PHOTO 1: LOCATION



PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: APACHE CANYON 35-07
API #: 05-071-09320
Insp. Doc. # 695100451



PHOTO 3: IMPACTED SOIL AROUND WELLHEAD A CHALKY RUST COLLARD IMPACTION TO THE LEFT OF WELLHEAD AND AN OILY IMPACTION TO THE RIGHT (WEST) OF WELLHEAD. DRIVEHEAD IS NOT RUNNING AT TIME OF INSPECTION.



PHOTO 4: ENGINE SKID HAS ROUGHLY 1 TO 1.5" OF OIL. IMPACTED SOIL ON SOUTH SIDE OF ENGINE SKID.

Inspection Photos

Location Name: APACHE CANYON 35-07

API #: 05-071-09320

Insp. Doc. # 695100451



PHOTO 5: IMPACTED SOIL TO NORTH OF SKID AND ALONG HYDRAULIC HOSES LEADING FROM SKID TO WELLHEAD



PHOTO 6: MOR IMPACTED SOIL ON NORTH SIDE OF SKID AND ON THE WEST SIDE OF SKID.



Inspection Photos

Location Name: APACHE CANYON 35-07

API #: 05-071-09320

Insp. Doc. # 695100451



PHOTO 7:UNUSED EQUIPMENT STORED ON LOCATION NEAR METER HOUSE. (2" POLLEY PIPE AND APPEARS TO BE SOME TELEMETRY EQUIPMENT).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources