

**Inspection Photos**  
**Location Name: APACHE CANYON 35-06**  
**API #: 05-071-08540**  
**Insp. Doc. # 695100455**



**PHOTO 1: LOCATION**



**PHOTO 2: METER HOUSE/WELL SIGN**

## Inspection Photos

Location Name: APACHE CANYON 35-06

API #: 05-071-08540

Insp. Doc. # 695100455



**PHOTO 3: PRODUCED WATER LEAKING FROM TBG PACKING INTO WELL CELLAR.**



**PHOTO 4: COMPRESSOR SKID IS FULL OF OIL AND TRASH CASING SUBSTANTIAL IMPACTED SOIL AROUND SKID. ENTIRE SKID AND ITS COMPONENTS ARE SATURATED WITH OIL.**





## Inspection Photos

Location Name: APACHE CANYON 35-06

API #: 05-071-08540

Insp. Doc. # 695100455



Colorado Oil & Gas Conservation Commission  
37.12887, -104.85951, 2140.0m, 213°  
2019/04/09 11:40:10



Colorado Oil & Gas Conservation Commission  
37.12887, -104.85951, 2140.0m, 26°  
2019/04/09 11:41:04

**PHOTO 5: IMPACTED SOIL EXTENDING THE ENTIRE LENGTH OF COMPRESSOR SKID FROM SKID TO THE SOUND WALL, WALL IS ALSO COATED WITH A SKIM OF OIL.**

**PHOTO 6: IT APPEARS THAT OIL IS BEING TRACKED FROM OTHERSIDE BY FOOT. ALL THE GRAVEL INSIDE SOUND WALLS IS IMPACTED.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: APACHE CANYON 35-06

API #: 05-071-08540

Insp. Doc. # 695100455



**PHOTO 7: MOR TRASH ON COMPRESSOR SKID.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources