

Inspection Photos
Location Name: APACHE CANYON 35-05
API #: 05-071-08542
Insp. Doc. # 695100457



PHOTO 1: LOCATION



PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: APACHE CANYON 35-05
API #: 05-071-08542
Insp. Doc. # 695100457



PHOTO 3: APPROXIMATELY 4' BY 2' AREA OF IMPACTED SOIL ON WEST SIDE OF WELLHEAD WITH WHAT APPEARS TO BE HYDRAULIC OIL FROM DRIVEHEAD OR HYDRAULIC HOSED



PHOTO 4: APPROXIMATELY 4' AREA OF IMPACTED SOIL ON NORTH SIDE OF METER HOUSE BENEATH SEPARATOR DRAIN. APPEARS BRODUCED CBM WATER IS BEING RELEASED FROM SEPARATOR.

Inspection Photos

Location Name: APACHE CANYON 35-05

API #: 05-071-08542

Insp. Doc. # 695100457



PHOTO 5: APPROXIMATELY 2' BY 2' AREA OF IMPACTED SOIL ON SOUTHEAST CORNER OF ENGINE SKID.



PHOTO 6: PHOTO SHOWING PIT LEVEL NOT FLUCTUATING DISPIE A SMALL STEADY STREAM OF PRODUCED CBM WATER FROM WELL BEING DISCHARGED INTO PIT.

Inspection Photos
Location Name: APACHE CANYON 35-05
API #: 05-071-08542
Insp. Doc. # 695100457



PHOTO 7: PHOTO SHOWING DISCARCH OF WATER BELOW LOCATION APPROXIMATELY 24 YDS OFF THE EAST SIDE OF LOCATION. IT APPEARS THAT PIT IS LEAKING PRODUCED CBM WATER.



PHOTO 8: PHOTO SHOWING MORE IMPACTED AREA AND DEAD PINON TREES IN IMPACTED AREA.

Inspection Photos

Location Name: APACHE CANYON 35-05

API #: 05-071-08542

Insp. Doc. # 695100457



PHOTO 9: MORE AREA IMPACTED.



PHOTO 10: SAME AREA OF PHOTO #7 FROM FARTHER DOWN THE HILL.

Inspection Photos
Location Name: APACHE CANYON 35-05
API #: 05-071-08542
Insp. Doc. # 695100457



PHOTO 11: PHOTO LOOKING UP A SEVERAL POINTS OF DISCHARGE FROM NORTHEAST OF LOCATION.



PHOTO 12: CLOSER PHOTO OF DISCHARGE TO THE NORTHEAST BELOW LOCATION.

Inspection Photos

Location Name: APACHE CANYON 35-05

API #: 05-071-08542

Insp. Doc. # 695100457



PHOTO 11: PHOTO LOOKING UP A SEVERAL POINTS OF DISCHARGE FROM NORTHEAST OF LOCATION.



PHOTO 14: MORE DEAD TREES.

Inspection Photos

Location Name: APACHE CANYON 35-05

API #: 05-071-08542

Insp. Doc. # 695100457



PHOTO 13: CLOSER VIEW OF DISCHARGE ON THE NORTHEAST SIDE BELOW LOCATION.



PHOTO 16: CLOSEST VIEW OF DISCHARGE ON NORTHEAST SIDE BELOW LOCATION.