



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x3)		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Appears to be stained soil in north heated seperator house. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/01/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel (x3)		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.367700,-104.682300
Comment:	Anchored				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	BV CONCRETE		
Comment:	Anchored				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	60 BBLs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 294786 Type: WELL API Number: 123-25554 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 294892 Type: WELL API Number: 123-25576 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 295200 Type: WELL API Number: 123-25687 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Monday, April 1, 2019 at approximately 13:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at Ikenouye F 29-23, 22 and Ikenouye F 28-33 (SRC Energy), at location#: 332782 in Weld County, Colorado.  While there, I observed 2 producing wells and one shut in well.  During this inspection the following possible compliance issues were observed:  1. Appears to be stained soil. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (Corrective action date: May 1, 2019) See attached photo #3.  <b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC# 672500500.</b>  <b>ALL CORRECTIVE ACTIONS TO PREVIOUS INSPECTION HAVE BEEN CORRECTED.</b>  A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p> <p>Continuing education inspection.</p>	santistb	04/01/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401994371	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782571">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782571</a>
679600557	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782564</a>
679600558	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782565">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782565</a>
679600559	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782566</a>