



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: fiberglass pipe next to WH building		
Corrective Action:	Comply with rule 603 f	Date:	05/03/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Submersible Pump	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0				,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)	
--------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	
-----------	--

Other (Content)	
-----------------	--

Other (Capacity)	
------------------	--

Other (Type)	
--------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	
-----------	--

Other (Content)	
-----------------	--

Other (Capacity)	
------------------	--

Other (Type)	
--------------	--

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

**Venting:**

Yes/No	NO			
--------	----	--	--	--

Comment:	
----------	--

Corrective Action:	Date:
--------------------	-------

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:		Date:

--	--	--

**Inspected Facilities**

Facility ID: 444708 Type: WELL API Number: 123-42698 Status: IJ Insp. Status: IJ

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: 2300

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>1806psig</u> (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg <u>4psig</u>	Previous Test Pressure _____	Inj Zone: <u>LYNS</u>
Brhd:	Pressure or inches of Hg <u>150psig</u>	Previous Test Pressure _____	Last MIT: <u>06/24/2016</u>
			AnnMTReq: <u>NO</u>

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Unused equipment: at time of inspection the was 2 joints of fiberglass pipe outside of WH building	silverr	04/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401995539	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783511">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783511</a>
688401756	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783508</a>