

Inspection Photos
Location Name: GE #19-6
Location ID: 308830



Photo 1 Sep/meter house



Photo 2 WH/HYD skid sound walls

Inspection Photos
Location Name: GE #19-6
Location ID: 308830



Photo 3 Unused equipment Sound walls



Photo 4 Pit

Inspection Photos
Location Name: GE #19-6
Location ID: 308830



Photo 5 Storm water Location water and sediment going into pit



Photo 6 stained soil around WH

Inspection Photos
Location Name: GE #19-6
Location ID: 308830



Photo 7 Storm water; sediment going into pit



Photo 8 Reel on slope of location carrying sediment into drainage need to redirect into proper rocked location drain

Inspection Photos
Location Name: GE #19-6
Location ID: 308830



Photo 9 proper location rocked drainage

