

Inspection Photos
Location Name: Hamil 19-16HA
API: 05-081-07822



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. Stained soil at wellhead.

Inspection Photos
Location Name: Hamil 19-16HA
API: 05-081-07822



Photo 3. Bucket and stained soil at exhaust.



Photo 4. Bucket for drips in separation equipment.