

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2019

Submitted Date:

04/04/2019

Document Number:

675002120

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312612 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222020	WELL	PA	10/16/2017	GW	077-08622	SOUTH SHALE RIDGE 10-15	PA

General Comment:

This is a follow up inspection from Doc#675001770 dated 1/16/19 . Required Corrective Action (s) items noted in previous inspections have not been satisfied, but have time remaining to meet corrective action date of 4/16/19

This well is included in the Administrative Order of Consent No. 1V-609.

Well was plugged on 10/16/17 . Form 6 (S) Doc#401554007 in process. Well surface evidence of well at time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment: No Emergency contact information or signage of any kind on location at present time

Corrective Action: Install sign to comply with Rule 210.b.

Date: 05/03/2019

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: Pipeline and riser left on location
Items remain on location from previous inspection #675001770 dated 1/16/19
(see photos 2-7)

Corrective Action: Comply with Rule 603.f .

Date: 04/16/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 222020 Type: WELL API Number: 077-08622 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was plugged on 10/16/17 . Form 6 (S) Doc#401554007 in process. Well surface evidine of well at time of inspection.

Corrective Action: Date: _____

Workover

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion not being controlled on the location at this time. Heavy erosion and movement of sediment from North and east hillsides onto location. . Sediment erodes across the location then moving off location on the west side and along both entrances onto and across access road then down the ravine. (See Photos 8-15)

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/03/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401995841	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783919
675002121	Inspection 675002120 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4783917