

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2019

Submitted Date:

04/05/2019

Document Number:

687904499**FIELD INSPECTION FORM**

Loc ID 326624 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		inspections@catamountep.com	All Inspections
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259893	WELL	PR	12/28/2001	GW	067-08426	CRIEGLER UTE FT 1	PR
438947	WELL	PR	01/01/2018	LO	067-09915	IGS 146	PR
441230	WELL	PR	01/01/2018	LO	067-09926	IGS 149	PR

General Comment:[This is an onsite inspection of the location as required. Downloadable photos at the end of this report.](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road access off county road.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Signs posted at wellheads.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards directly on tank.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Emergency contact information posted on signs.	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 3		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	3" steel discharge to dogleg.		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	3" steel from wellhead to separator.		
Corrective Action:		Date:	
Type: Compressor	# 2		

Comment:	2" steel from wellhead to tank.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 3			
Comment:	2" steel fuel gas from separator to engine.		Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 3			
Comment:	Wellheads with bradenhead access.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 3			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Secondary containment has been compromised.			
Corrective Action:	Comply with Rule 906.d.(1)			Date: 05/05/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 259893 Type: WELL API Number: 067-08426 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 438947 Type: WELL API Number: 067-09915 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 441230 Type: WELL API Number: 067-09926 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401998512	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786844
687904500	Secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786837
687904501	Secondary containment breach	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786838
687904502	Location Overview	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786839
687904504	Secondary containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4786840