

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Colorado Oil and Gas Conservation Commission
37.07846, -104.95774, 2485.5m
Apr 11, 2019 11:21:50

Photo 1 Sep/meter house.



Colorado Oil and Gas Conservation Commission
37.07853, -104.9578, 2484.9m
Apr 11, 2019 11:22:13

Photo 2 loc pic. Rods appear to have been removed from well. Pump jack not being used.

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Photo 3 Unused equipment; PU, Cement base, horses head and guard.



Photo 4 Stained soil around Liquid ring skid.

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Photo 5 North east corner fill side of location appears to have broken away from location and slid down hill side.

Photo 6 North east corner fill side of location appears to have broken away from location and slid down hill side

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Photo 7 North east corner fill side of location appears to have broken away from location and slid down hill side.

Photo 8 North east corner fill side of location appears to have broken away from location and slid down hill side and knocked down trees.

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Photo 9 South east corner fill side of location appears to have broken away from location and slid down hill side.

Photo 10 South east corner fill side of location appears to have broken away from location and slid down hill side.

Inspection Photos
Location Name: AC #14-16V
Location ID: 307892



Photo 11 South east corner fill side of location appears to have broken away from location and slid down hill side.