

Inspection Photos
Location Name: AC# 24-02V
Location ID: 307884



Photo 1 Sep/meter house



Photo 2 Unused, unmarked not LOTO risers

Inspection Photos
Location Name: AC
Location ID:307884



Colorado Oil and Gas Conservation Commission
37.0741, -104.94311, 2357.7m
Apr 11, 2019 13:44:23



Colorado Oil and Gas Conservation Commission
37.07407, -104.94335, 2356.6m
Apr 11, 2019 13:44:57

Photo 3 Liquid ring skid. Unused equipment (HYD skid, PC Drive). Unused, unmarked and not LOTO riser.

Photo 4 Unused equipment (cement blocks)

Inspection Photos
Location Name: AC #24-02V
Location ID:307884



Photo 5 Storm water; location is eroding down hill side.

Photo 6 Berms around outer edge of fill side of location.

Inspection Photos
Location Name: AC #24-02V
Location ID:307884



Colorado Oil and Gas Conservation Commission
37.07402, -104.94331, 2355.5m
Apr 11, 2019 13:46:27

Photo 7 Storm water; Appears ditch line is settling deep ruts