

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 05/11/2019
Emergency Contact Number:			
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 04/12/2019
Good Housekeeping:			
Type	TRASH		
Comment:	Door of sep/meter house; Inspector opeded door to check meter and door fell on inspector hinges were not screwed in.		
Corrective Action:	Comply with 603 f		Date: 04/25/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment; 1" pipe on location		
Corrective Action:	Comply with rule 603 f		Date: 05/11/2019
Type	OTHER		
Comment:	stained soil around liquid ring riser		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A		Date: 05/11/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Compressor	# 1		
Comment: Liquid ring			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment: HYD Skid			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 05/02/2019
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm			
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 282649 Type: WELL API Number: 071-08687 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday April 11, 2019 at approximately 1311 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site AC # 24-4, at API # 05-071-08687 in Las Animas County Colorado. While there, I observed a production well site. During this inspection the following possible compliance issues were observed: Unused Equipment; Rule 603 f Corrective action date of 5-11-19 See photo 2 Stained soil; Rule 907 A Corrective action date of 5-11-19 See photo 3 Guy line anchor; Rule 1003 a. Corrective action date of 5-2-19 See photo 6 Trash; rule 603 f Corrective action date of 4-25-19 see photo 1 Location sign not posted; Rule 210 b Corrective action date of 5-11-19 See photo 1 Emergency contact number; Rule 210 b Corrective action date of 4-12-19 see photo 1 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401816	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792642