

PIT STATUS EVALUATION FORM

Facility ID: 115141

Pit Name: COGGINS 1-10

☐ Duplicate Record(s) Pit #



Legend

- Producing or Shut In Well
- Temp Aban Well
- Abandoned Well
- Dry & Aban Well
- Earthen Pit
- Culvert
- Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: SMITH ENERGY CORP
T: 6S R: 64W Sec: 10 QQ: SWSW 6th Meridian
Latitude: 39.536938 Longitude: -104.547805 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

☐ Active

☐ Form 15: Pit Permit #581286 (1982) new Assoc. Well Seq No(s) 06383 (9-5-81) PR
☐ Other documentation FIR # 441047 (6-20-95)
☐ Aerial photo verification

☒ Closed

☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice _____
☐ Rule 903a.(2)B _____
☐ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) _____
☒ Other documentation FIR # 20088218 (1-30-06) no pit found

☐ Abandoned

☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs

☒ Site Visit
☐ No Site Visit
☐ Add'l Review

☐ Unknown

Notes: FIR (1995) "production pit doesn't have screen over it - small amount of water"
FIELD VISIT 6-3-2008: no sign of pit