

Inspection Photos
Location Name: HR#29-14 and HR#29-14V
Location ID: 333804



Photo 1 Duel Sep/meter house for HR#29-14 and HR#29-14V,15bbl produced water tank and electric panel.

Photo 2 HR#29-14 PU

Inspection Photos
Location Name: HR#29-14 and HR#29-14V
Location ID: 333804



Colorado Oil and Gas Conservation Commission
37.05055, -104.91283, 2475.7m
Apr 12, 2019 11:26:25



Colorado Oil and Gas Conservation Commission
37.05046, -104.91271, 2468.2m
Apr 12, 2019 11:27:27

Photo 3 Stained soil around HR#29-14 WH.

Photo 4 HR#29-14V WH. Unused, unmarked and not LOTO risers.

Inspection Photos
Location Name: HR#29-14 and HR#29-14V
Location ID: 333804



Photo 5 HR#29-14 Transfer station

**Photo 6 Unused equipment Filter pot, hose and metal.
Inadequate berm around tank.**

Inspection Photos
Location Name: HR#29-14 and HR#29-14V
Location ID: 333804



Colorado Oil and Gas Conservation Commission
37.05075, -104.9127, 2467.3m
Apr 12, 2019 11:28:58



Colorado Oil and Gas Conservation Commission
37.05077, -104.9128, 2466.9m
Apr 12, 2019 11:29:25

Photo 7 House Keeping What appears to be used filter pot filters laying on ground and unused unloading spill container.

Photo 8 Reclaimed production pit.