

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2019

Submitted Date:

04/08/2019

Document Number:

687904515

FIELD INSPECTION FORM

Loc ID 311909 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Inspections, All		inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216324	WELL	PR	08/26/1993	GW	067-07930	HARMON GAS UNIT A 2	PR
435727	WELL	PR	08/12/2017	GW	067-09901	IGE 141	PR

General Comment:

[This is an onsite inspection of the location as required. Downloadable photos at the end of this inspection report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road through locked gate.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign is posted at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information is posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Secondary containment has tires in it.		
Corrective Action:	Tires are trash. Comply with Rule 603.f.		Date: 04/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellhead with PVC bradenhead access.		
Corrective Action:			Date:

Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment of IGE 141 produced water tank has multiple tears in liner on base and on walls.			
Corrective Action:	Repair or replace secondary containment liner to comply with Rule 906.d.(1)			Date: 05/08/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 216324 Type: WELL API Number: 067-07930 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 435727 Type: WELL API Number: 067-09901 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention under oil day tanks ofr engines.
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402000500	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788234
687904516	Location overview	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788224
687904517	Tires in secondary containment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788225
687904518	Liner failure northwest corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788226
687904519	Liner base failure northwest corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788227
687904520	Liner failure southeast corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788228
687904521	Liner failure along northern wall	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788229