

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2019

Submitted Date:

04/08/2019

Document Number:

692601624

**FIELD INSPECTION FORM**

Loc ID 321070 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 76859  
Name of Operator: SCHREIDER & COMPANY INC  
Address: 240 W JESSUP ST  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 15 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Arnold, Diana	303-659-8203	darnold@agcsi.com	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205953	WELL	SI	12/01/2018	GW	009-06368	HETRICK 1-29	SI

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on water tank		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 05/05/2019
Type	WELLHEAD		
Comment:	Lease sign mounted to meter run door. Meter run housing laying on the ground		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 05/05/2019

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Dead weeds across location		
Corrective Action:	Comply with Rule 603.f.		Date: 05/05/2019
Type	DEBRIS		
Comment:	Old gas scrubber, wire panels, metal panels and lumber laying around location.		
Corrective Action:	Comply with Rule 603.f.		Date: 05/05/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Metal panels around entire location		
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Pump Jack	# 1			
Comment:	Parkersburg unit			
Corrective Action:				Date:
Type: Vertical Separator	# 1			
Comment:	Vertical gas separator next to meter run			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.320760,-102.073470
Comment:	Fiberglass open top water tank				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	No berms around water tank			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 05/05/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 205953 Type: WELL API Number: 009-06368 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Well is SI at time of inspection](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402000186	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788079">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788079</a>
692601628	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788077">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4788077</a>