

**Inspection Photos**  
**Location Name: APACHE CANYON 26-16V**  
**API #: 05-071-07558**  
**Insp. Doc. # 695100497**



Colorado Oil & Gas Conservation Commission  
37.11754, -104.92483, 224°  
2019/04/12 13:11:18



Colorado Oil & Gas Conservation Commission  
37.04939, -104.95825, 2450.0m, 336°  
2019/04/12 13:11:32

**PHOTO 1: LOCATION**

**PHOTO 2: METER HOUSE/WELL SIGN**

## Inspection Photos

Location Name: APACHE CANYON 26-16V

API #: 05-071-07558

Insp. Doc. # 695100497



Colorado Oil & Gas Conservation Commission  
37.04923, -104.95823, 2449.0m, 293°  
2019/04/12 13:12:05



Colorado Oil & Gas Conservation Commission  
37.04922, -104.95824, 2450.0m, 200°  
2019/04/12 13:12:33

**PHOTO 3: THERE IS APP. 2' AREA OF IMPACTED SOIL ON SOUTHEAST CORNER OF COMPRESSOR SKID NEAR SKID DRAIN PLUG.**

**PHOTO 4: THERE IS APP. 2' AREA ON IMPACTED SOIL AROUND BASE OF FUEL GAS SEPARATOR ON PRIME MOVER ENGINE SKID. ENGINE SKID HAS APP. 1' STANDING OIL IN SKID CONTAINMENT.**



## Inspection Photos

Location Name: APACHE CANYON 26-16V

API #: 05-071-07558

Insp. Doc. # 695100497



**PHOTO 5: APP. A 8" ROUND AREA OF IMPACTED SOIL ON WEST END OF PRIME MOVER ENGINE SKID.**

