

**Inspection Photos**  
**Operator: Enervest Operating**  
**Location/API #: 067-05192**  
**Date: 4-9-2019**



Photo 1. View of an erosional channel forming around project facilities within the western project area.



Photo 2. View of erosional channeling and sediment deposition along the northern edge of the working area.



Photo 3. View of erosional channeling within the northeastern project area.



Photo 4. View of erosional rilling within the eastern project area.



Photo 5. View of condition of reference area at this time.