

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	IMPACTED SOIL AROUND WELLHEAD A CHALKY RUST COLLARD IMPACTION TO THE LEFT OF WELLHEAD AND AN OILY IMPACTION TO THE RIGHT (WEST) OF WELLHEAD. DRIVEHEAD IS NOT RUNNING AT TIME OF INSPECTION.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/09/2019
Type	UNUSED EQUIPMENT		
Comment:	UNUSED EQUIPMENT STORED ON LOCATION NEAR METER HOUSE. (2" POLLEY PIPE AND APPEARS TO BE SOME TELEMETRY EQUIPMENT).		
Corrective Action:	Comply with Rule 603.f .	Date:	05/09/2019
Type	OTHER		
Comment:	ENGINE SKID HAS ROUGHLY 1 TO 1.5" OF OIL. IMPACTED SOIL ON SOUTH SIDE OF ENGINE SKID. IMPACTED SOIL TO NORTH OF SKID AND ALONG HYDRAULIC HOSES LEADING FROM SKID TO WELLHEAD MORE IMPACTED SOIL ON NORTH SIDE OF SKID AND ON THE WEST SIDE OF SKID.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	05/09/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:		corrective date
Type: Ancillary equipment	# 1	
Comment:	TELEMETRY EQUIPMENT	
Corrective Action:		Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 290929 Type: WELL API Number: 071-09320 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002169	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789655
695100452	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789644