

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

695100455**FIELD INSPECTION FORM**
 Loc ID 308735 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280079	WELL	PR	07/01/2011	GW	071-08540	APACHE CANYON 35-06	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PRODUCED WATER LEAKING FROM TBG PACKING INTO WELL CELLAR.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>05/09/2019</u>
Type	TRASH		
Comment:	MORE TRASH ON COMPRESSOR SKID.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>04/20/2019</u>
Type	OTHER		
Comment:	COMPRESSOR SKID IS FULL OF OIL AND TRASH CASING SUBSTANTIAL IMPACTED SOIL AROUND SKID. ENTIRE SKID AND ITS COMPONENTS ARE SATURATED WITH OIL. IMPACTED SOIL EXTENDING THE ENTIRE LENGTH OF COMPRESSOR SKID FROM SKID TO THE SOUND WALL, WALL IS ALSO COATED WITH A SKIM OF OIL. IT APPEARS THAT OIL IS BEING TRACKED FROM OTHERSIDE BY FOOT. ALL THE GRAVEL INSIDE SOUND WALLS IS IMPACTED.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Comply with COGCC rule 1002 F (2) B Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs		Date: <u>05/09/2019</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	NO FORM 4 SUNDRY APPROVED ON RECORD		
Corrective Action:	COMPLY WITH RULE 331		Date: <u>05/09/2019</u>
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 280079	Type: WELL	API Number: 071-08540	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002171	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789657
695100456	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789646