

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

695100457**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 308737 Beardslee, Tom 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280077	WELL	PR	07/01/2011	GW	071-08542	APACHE CANYON 35-05	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	APPROXIMATELY 4' BY 2' AREA OF IMPACTED SOIL ON WEST SIDE OF WELLHEAD WITH WHAT APPEARS TO BE HYDRAULIC OIL FROM DRIVEHEAD OR HYDRAULIC HOSED. APPROXIMATELY 2' BY 2' AREA OF IMPACTED SOIL ON SOUTHEAST CORNER OF ENGINE SKID.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: 05/09/2019
Type	OTHER		
Comment:	APPROXIMATELY 4' AREA OF IMPACTED SOIL ON NORTH SIDE OF METER HOUSE BENEATH SEPARATOR DRAIN. APPEARS BRODUCED CBM WATER IS BEING RELEASED FROM SEPARATOR.		
Corrective Action:	IMMEDIATELY STOP DISCHARGING PRODUCED CBM WATER ON LOCATION. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: 05/09/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 280077	Type: WELL	API Number: 071-08542	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 291919Lat: 37.130590Long: -104.863000

Reference Point: _____

Other: _____

Length: 58Width: 27**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:Fencing Type: None

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment:

PHOTO SHOWING PIT LEVEL NOT FLUCTUATING DISPIE A SMALL STEADY STREAM OF PRODUCED CBM WATER BEING DISCHARGED INTO PIT. APPEARS PRODUCED CBM WATER IS SEEPING OUT OF PIT BELOW LOCATION APPROXIMATELY 24 YDS OFF THE EAST SIDE AND NORTHEAST SIDE OF LOCATION.

Corrective Action

Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 04/10/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002172	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789658
695100458	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789647