

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

696100734**FIELD INSPECTION FORM**
 Loc ID 330952 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256780	WELL	PR	01/01/2017	OW	123-19925	STATE 5519 8-34	PR

General Comment:

This is a WELL Inspection.

Centralized Battery serves 3 Location IDs (330664, 330951, 330952). (2-wells: PR, 1-well: SI).

Centralized Battery Formerly served 1 Location ID (331353). (1-well: PA).

Refer to FIR #696100732 and/or Location ID #330664 for Battery / Facility, Equipment info.

Location					
Lease Road:					
Type	Access				
comment:	Adequate				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency number NOT complete or Legible at well. See photo #1. Refer to Rule 210.e for guidance. (30 Days).				
Corrective Action:	Post Legible Emergency contact number at well to comply with Rule 210.e.				Date: 05/09/2019
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	Refer to FIR #696100732 and/or Location ID #330664 for additional Fencing info.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Iron panel				
Corrective Action:					Date:
Equipment:					
					corrective date
Type:		#			
Comment:	Refer to FIR #696100732 and/or Location ID #330664 for additional Equipment info.				
Corrective Action:					Date:
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:					Date:
Type: Other		# 1			
Comment:	Bradenhead appears plumbed to surface.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.410068,-104.455435

Comment:	Centralized Battery serves 3 Location IDs (330664, 330951, 330952). Centralized Battery Formerly served 1 Location ID (331353). Refer to FIR #696100732 and/or Location ID #330664 for Tanks & Berms info.	
Corrective Action:		Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	256780	Type:	WELL	API Number:	123-19925	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On TUE APR 09, 2019 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at: Facility ID #330952, STATE 5519-65N63W /8SWSE. Operated by PDC Energy. While there I observed: Well(s) Producing. Routine Inspection. 1 - Corrective Actions observed. 1.) Emergency number not legible or missing at wellsite: Rule 210.e. Corrective action date of 05-09-19. See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002290	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789703
696100735	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789701