

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

696100736**FIELD INSPECTION FORM**
 Loc ID 330951 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256779	WELL	PR	01/01/2017	OW	123-19924	STATE 5519 8-43	PR

General Comment:[This is a WELL Inspection.](#)[Well is SI.](#)[Centralized Battery serves 3 Location IDs \(330664, 330951, 330952\). \(2-wells: PR, 1-well: SI\).](#)[Centralized Battery Formerly served 1 Location ID \(331353\). \(1-well: PA\).](#)[Refer to FIR #696100732 and/or Location ID #330664 for Battery / Facility, Equipment info.](#)

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency number NOT complete or Legible at well. See photo #1. Refer to Rule 210.e for guidance. (30 Days).			
Corrective Action:	Post Legible Emergency contact number at well to comply with Rule 210.e. Re-attach sign to well fence.			Date: 05/09/2019
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused automation & downhole equipment, motor valve at wellsite. Refer to Rule 603.f for guidance. (30 Days). See photo #1.			
Corrective Action:	Remove Unused automation & downhole equipment, motor valve at wellsite. Comply w/ Rule 603.f.			Date: 05/09/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel			
Corrective Action:				Date:
Type	OTHER			
Comment:	Refer to FIR #696100732 and/or Location ID #330664 for additional Fencing info.			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type:	#			
Comment:	Refer to FIR #696100732 and/or Location ID #330664 for additional Equipment info.			
Corrective Action:				Date:

Type: Other	# 1	
Comment:	Bradenhead appears plumbed to surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.410068,-104.455435
Comment:	Centralized Battery serves 3 Location IDs (330664, 330951, 330952). Centralized Battery Formerly served 1 Location ID (331353). Refer to FIR #696100732 and/or Location ID #330664 for Tanks & Berms info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities										
Facility ID:	256779	Type:	WELL	API Number:	123-19924	Status:	PR	Insp. Status:	PR	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS				
Comment:		<div>SI. Observed production valves shut at well & separator.</div>								
Corrective Action:		<div></div>						Date:		<div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On TUE APR 09, 2019 at approximately 15:31 hrs. I, Bret Evins, conducted an on-site inspection at: Facility ID #330951, STATE 5519-65N63W /8NESE. Operated by PDC Energy. While there I observed: Well(s) SI. Routine Inspection. 2 - Corrective Actions observed. 1.) Emergency number not legible or missing at wellsite: Rule 210.e. Corrective action date of 05-09-19. See photo #1. 2.) Unused automation & downhole equipment, motor valve at wellsite: Rule 603.f. Corrective action date of 05-09-19. See photo #1.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402002291	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789704
696100737	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4789702