

Inspection Photos
Operator: BP America
Location/API #: 067-06295
Date: 4-9-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of erosional channeling and sediment discharge within the southern project area.



Photo 5. View of erosional channeling and sediment deposition within the southeastern portion of the working area.



Photo 6. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 200 individuals observed.