

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

679600599

FIELD INSPECTION FORM

Loc ID 322898 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1001 NOBLE ENERGY WAY
 City: HOUSTON State: TX Zip: 77070

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|--|-----------------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | ALL INSPECTIONS |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 244440 | WELL | SI | 01/01/2017 | GW | 123-12234 | STEWART 2 | TA |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | WELLHEAD | | |
| Comment: | No sign at wellhead. See attached photo. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 05/11/2019 |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | 6' chain link . | | |
| Corrective Action: | | Date: | |

Equipment:

| Type | # | corrective date |
|-----------------------------|-----|-----------------|
| Horizontal Heated Separator | # 0 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Bird Protectors | # 0 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Emission Control Device | # 0 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Gas Meter Run | # 0 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|----------------------|----------|------|---------|--------|
| PRODUCED WATER | 0 | | | | |
| Comment: | <input type="text"/> | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|--|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|-----------|---|----------|------|---------|--------|--|
| CRUDE OIL | 0 | | | | | |

| | | | |
|--------------------|--|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |

Paint

| | | | |
|------------------|--|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|--|--|-------|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 244440 Type: WELL API Number: 123-12234 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA. MIT requirement waived per variance doc#401474555.

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>COGCC Inspection Report Summary On Thursday, April 11, 2019 at approximately 12:49, I, Inspector Brittani Santistevan, conducted an on-site inspection at STEWART 2 (Noble), at Location #: 322898 in WELD COUNTY Colorado. While there, I observed a temporarily abandoned wellhead. During this inspection the following possible compliance issues were observed: 1. No sign at wellhead. Install sign to comply with Rule 210.b. (Corrective Action Date: May 11, 2019) See attached photo #1. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing education inspection.</p> | santistb | 04/11/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 679600600 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797354 |