

Inspection Photos
Operator: BP America
Location/API #: 067-06340
Date: 4-9-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of the eastern project area from the northeastern corner facing southward. Russian thistle debris needs to be removed.



Photo 4. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 150 individuals present.



Photo 5. View of erosion within the northwestern portion of the project area, where stormwater flows from the access road appear to erode the road surface and carry sediment and debris downslope toward the northern drainage.



Photo 6. View of erosion down-slope from photo 5, at the edge of the project area, adjacent to a drainage.