

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2019

Submitted Date:

04/16/2019

Document Number:

687904585**FIELD INSPECTION FORM**
 Loc ID 325723 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215294	WELL	PR	02/20/1990	GW	067-06899	HUBERT MORRISON A 1	PR

General Comment:[This is an onsite inspection of this location as required. Photos are at the end of this inspection report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 6		
Comment:	1-4" steel flowline from wellhead to separator. 1-3" steel flowline from separator to meter house. 1-2" steel flowline from meter house to offsite dogleg. 1-2" steel flowline from separator dump valve to offsite produced water gathering system. 1-1" steel flowline from separator to pumpjack engine fuel gas. * 1-1" steel flowline from separator to domestic gas tap.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with PVC bradenhead access.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pump jack has localized areas around gas powered engine of oily waste and stained gravel that needs to be cleaned up and removed.		
Corrective Action:	Clean up areas of stained gravel in accordance with Rule 907.e. and make sure all fittings are properly secure in accordance with Rule 605.d.		Date: 05/16/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215294	Type:	WELL	API Number:	067-06899	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil day tank.
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Rip Rap	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904586	Gravel staining around fuel gas scrubber	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797733
687904587	Gravel staining	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797734
687904588	Engine leaks.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797735
687904589	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4797736