

Inspection Photos
Operator: BP America
Location/API #: 067-05226
Date: 4-9-2019



Photo 1. View of the wellhead marker facing southward. Revegetation is sparse around wellhead. Gravel observed.



Photo 2. View of former access road still in place, facing southward.



Photo 3. View of culvert and access road still in place, facing southwestward.



Photo 4. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 50 individuals present.



Photo 5. View of erosional rilling within the southern project area.



Photo 6. View of area with poor revegetation and gravel present within the southern project area.