

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2019

Submitted Date:

04/08/2019

Document Number:

675002140

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
312610 \_\_\_\_\_ Wentzel, Dougo \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, DNR		dnr_cogccengineering@state.co.us	<a href="#">All Engineering</a>
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Peicka, Conor		conor.pesicka@state.co.us	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Graves, Jim		mrinc20@qwestoffice.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222012	WELL	SI	05/01/2010	GW	077-08614	SOUTH SHALE RIDGE 5-23	TA

**General Comment:**

This is a follow up inspection from [Doc#689401640](#) dated 9/25/18 . Required Corrective Action (s) items noted in previous inspections have not been satisfied.  
This well is listed on AOC 1V-609

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	See storm water		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No sign at well head at this time.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 05/10/2019
Type	BATTERY		
Comment:	No sign at tank battery. Tank is not in containment and appears to be stored on location at this time. See house keeping		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	See signs /Markers under wellhead		Date: _____
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	All Production equipment stored on location		
Corrective Action:	Comply with Rule 603.f .		Date: 07/10/2019
Type	DEBRIS		
Comment:	Weeds and vegetation on location		
Corrective Action:	Comply with Rule 603.f .		Date: 10/08/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	#		corrective date
Comment:	See Housekeeping		
Corrective Action:			Date:
<b>Tanks and Berms:</b>			
Contents	#	Capacity	Type
OTHER			
Comment:	See house keeping		

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 222012 Type: WELL API Number: 077-08614 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: All production equipment has been diconenected and removed from wellhead, noted on previous inspection Doc#689400348 from 9/26/17.  
No current MIT on record or delinquent as required by Rule 326c

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan. Date: 10/08/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			
Compaction	Fail					
Gravel	Fail					

Comment: Stormwater erosion is not being controled at this time  
Erosion and sediment moving onto location from entrance  
Erosion and sediment moving across location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/10/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402003430	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790735">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790735</a>
675002141	Inspection 675002140 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790716</a>