

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

675002143

**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 312611      Wentzel, Dougo      2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO      State: CO      Zip: 81137

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11      Number of Comments

2      Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Colby, Lou		lou.colby@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	970-244-3041	bhartman@blm.gov	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222013	WELL	SI	05/01/2012	GW	077-08615	SOUTH SHALE RIDGE 9-22	TA

**General Comment:**

Routine FIU General Field Inspection  
 Form 06 (S) In progress doc#401132853 dated 10/25/2016  
 This well is not included in the Administrative Order of Consent No. 1V-609.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	There is no signage on location at this time		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 05/10/2019

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked risers left on location		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser		Date: 04/19/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	#		
Comment:	No production equipment on location at this time		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222013	Type:	WELL	API Number:	077-08615	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____									
<u>Comment:</u> Well was plugged 10/13/17. Form 6 (S) Doc#401132853, Previous inspection 689400347 dated 9/27/17 No production equipment on location									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
Compaction	Pass					

Comment: [Stormwater being controlled by vegetation.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402003431	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790736</a>
675002144	Inspection 675002143 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790717">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4790717</a>