

Inspection Photos

API: 05-071-08419

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/16/2019

Inspection Photos



Photo 1. Facing northwest along the main road at the gate of Cherry canyon. Stormwater appears to have flowed down the road from a plugged culvert. There is vehicle rutting and erosion in this area.

Inspection Photos



Photo 2. The culvert has been plugged up at the stream crossing causing stormwater to flow down the road.

Inspection Photos



Photo 3. Another culvert up the main road is filled in with sediment.

Inspection Photos



Photo 4. Further up the road is another culvert that is halfway full of sediment.

Inspection Photos



Photo 5. Erosion has deepened the side of the access road near the location. BMP's are needed to prevent further erosion.

Inspection Photos



Photo 6. There are erosion issues off the east side of the pad.

Inspection Photos



Photo 7. The door on the trash container is open. It was noticed that there was some trash that blew out.

Inspection Photos



Photo 8. The berm around the soil pile has been removed.

Inspection Photos



Photo 9. Pit at the location has 2ft. Freeboard and marker.

Inspection Photos



Photo 10. South access road has signs of erosion. BMP's are needed to prevent further erosion.

Inspection Photos



Photo 11. The culvert at the access road has had erosion issues. More rip/rap may be needed in this area.