

Inspection Photos
Location Name: CRYSTAL 13-4
API #: 05-071-06360
Insp. Doc. # 695100528



Colorado Oil & Gas Conservation Commission
37.19894, -104.68222, 2069.0m, 209°
2019/04/17 13:05:29

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.19872, -104.68215, 2065.0m, 198°
2019/04/17 13:05:53

PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: CRYSTAL 13-4
API #: 05-071-06360
Insp. Doc. # 695100528



PHOTO 3: IMPACTED SOIL ALL AROUND COMPRESSOR SKID



PHOTO 4: IMPACTED SOIL ON WEST SIDE OF COMPRESSOR PRIME MOVER SKID.

Inspection Photos
Location Name: CRYSTAL 13-4
API #: 05-071-06360
Insp. Doc. # 695100528



PHOTO 5: IMPACTED SOIL ON NORTH SIDE OF COMPRESSOR PRIME MOVER SKID.



PHOTO 6: IMPACTED SOIL ON SOUTH SIDE OF COMPRESSOR PRIME MOVER SKID.

Inspection Photos
Location Name: CRYSTAL 13-4
API #: 05-071-06360
Insp. Doc. # 695100528



PHOTO 7: IMPACTED SOIL ON NORTH SIDE OF PUMPJACK HYDRAULIC MOTOR.



PHOTO 8: APP. 2" OF STANDING WATER WITH OIL CONTAMINATION IN COMPRESSOR SKID IS WITHIN APP. 2" FROM RUNNING OVER