

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

687904549**FIELD INSPECTION FORM**Loc ID 333472 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment                               |
|------------------|--------------|-----------------------------|---------------------------------------|
| Labowskie, Steve |              | steve.labowskie@state.co.us |                                       |
| Inspections, All |              | SanJuanCOGCC@bp.com         | <a href="#">All Inspections</a>       |
| Beebe, Sabre     | 970-779-9398 | Sabre.Beebe@bpx.com         | <a href="#">SW Inspection Reports</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 289441      | WELL | PR     | 08/01/2017  | GW         | 067-09326 | COUCH 01-16U 2 | PR          |
| 289442      | WELL | PR     | 02/22/2007  | GW         | 067-09325 | COUCH 01-16U 3 | PR          |
| 289443      | WELL | PR     | 02/22/2007  | GW         | 067-09324 | COUCH 01-16U 4 | PR          |

**General Comment:**[This is an onsite inspection of this location as required. Photos are at the end of this inspection report.](#)

| Location   |   |        |  |                  |
|--|---|--------|--|------------------|
| <b>Lease Road:</b>                                     |   |        |  |                  |
| Type   | Access  |        |  |                  |
| comment:   | Gravel road off county road.  |        |  |                  |
| Corrective Action                                      | L   |        |  | Date:            |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                  |
| <b>Signs/Marker:</b>                                   |   |        |  |                  |
| Type   | WELLHEAD  |        |  |                  |
| Comment:   | Couch 01-16U 4 location sign is missing. The other 2 signs are at the entrance of the location. Need to install missing sign. |        |  |                  |
| Corrective Action:                                     | Comply with Rule 210.b.   |        |  | Date: 05/11/2019 |
| Emergency Contact Number:                              |   |        |  |                  |
| Comment:   | Emergency contact information posted on signs that are still at location.   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date: _____      |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                  |
| <b>Spills:</b>   |   |        |  |                  |
| Type   | Area  | Volume |  |                  |
| In Containment: No                                     |   |        |  |                  |
| Comment:   |   |        |  |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |                  |
| <b>Fencing/:</b>                                       |   |        |  |                  |
| Type   | WELLHEAD  |        |  |                  |
| Comment:   | Cattle panels   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| Type   | SEPARATOR   |        |  |                  |
| Comment:   | Cattle panels   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| Type   | TANK BATTERY  |        |  |                  |
| Comment:   | Cattle panels   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| <b>Equipment:</b>                                      |   |        |  |                  |
| Type: Gas Meter Run                                    | # 3   |        |  | corrective date  |
| Comment:   |   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| Type: Bird Protectors                                  | # 2   |        |  |                  |
| Comment:   | On separator stacks.  |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| Type: Vertical Heated Separator                        | # 2   |        |  |                  |
| Comment:   |   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |

|                                   |   |       |
|-----------------------------------|---|-------|
| Type: Pump Jack                   | # 2   |       |
| Comment:                          | Linear rod pump.  |       |
| Corrective Action:                |   | Date: |
| Type: Other                       | # 1   |       |
| Comment:                          | MCC for electric VFD driven motors.   |       |
| Corrective Action:                |   | Date: |
| Type: Horizontal Heated Separator | # 1   |       |
| Comment:                          |   |       |
| Corrective Action:                |   | Date: |
| Type: Flow Line                   | # 12  |       |
| Comment:                          | 3-3" steel lines from wellheads to separators. 3-2" steel, manual line dumps to produced water tanks. 3-2" steel, separator level control dumps to produced water tanks. 3-3" steel lines from separator through meter house. 2-4" steel lines from meter house to off site dogleg. |       |
| Corrective Action:                |   | Date: |
| Type: Ancillary equipment         | # 3   |       |
| Comment:                          | Wellheads with PVC bradenhead access.   |       |
| Corrective Action:                |   | Date: |

**Tanks and Berms:**

| Contents           | #     | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|-------|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1     | <100 BBLS | PBV STEEL |         | ,      |
| Comment:           |       |           |           |         |        |
| Corrective Action: | Date: |           |           |         |        |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: | Date:    |                     |                     |             |

**Venting:**

|                    |       |  |
|--------------------|-------|--|
| Yes/No             | NO    |  |
| Comment:           |       |  |
| Corrective Action: | Date: |  |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities  |            |                       |                             |
|-----------------------|------------|-----------------------|-----------------------------|
| Facility ID: 289441   | Type: WELL | API Number: 067-09326 | Status: PR Insp. Status: PR |
| <b>Producing Well</b> |            |                       |                             |
| Comment:              | Producing. |                       |                             |
| Corrective Action:    |            | Date:                 |                             |
|                       |            |                       |                             |
| Facility ID: 289442   | Type: WELL | API Number: 067-09325 | Status: PR Insp. Status: PR |
| <b>Producing Well</b> |            |                       |                             |
| Comment:              | Producing. |                       |                             |
| Corrective Action:    |            | Date:                 |                             |
|                       |            |                       |                             |
| Facility ID: 289443   | Type: WELL | API Number: 067-09324 | Status: PR Insp. Status: PR |
| <b>Producing Well</b> |            |                       |                             |
| Comment:              | Producing. |                       |                             |
| Corrective Action:    |            | Date:                 |                             |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402005454    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792271">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792271</a> |
| 687904550    | Location.            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792256">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792256</a> |
| 687904551    | Missing Sign.        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792257</a> |