

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

687904562

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
306809 \_\_\_\_\_ Stewart, Joseph \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 19 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267809	WELL	PR	02/01/2017	GW	067-08809	GOSNEY COM A 2	PR
411817	WELL	PR	08/27/2010	GW	067-09711	GOSNEY COM A 3	PR
411818	WELL	PR	08/19/2013	GW	067-09712	GOSNEY COM A 4	PR

**General Comment:**

This is an onsite inspection of location as required. Photos at the end of this inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access road on private ranch.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Gosney Com A4 location sign is missing. Other location signs at entrance.		
Corrective Action:	Replace sign to comply with Rule 210.b.		Date: 05/11/2019
Type	TANK LABELS/PLACARDS		
Comment:	Posted on produced water tank and free standing sign.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on both signs that are still on location.		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellheads, seperators, compressor and produced water tank.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 3		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	MCC for electric VFD driven motors and pumps.		
Corrective Action:			Date:
Type: Flow Line	# 15		
Comment:	3-4" steel flowlines from wellheads to separator. 3-2" steel flowlines for blowdown to produced water tank. 3-2" steel flowlines for seperator dump valves into produced water tank. 1-1" steel fuel gas service for compressor. 3-3" steel flowlines from seperator outlet to common 1-4" common header with compression to dogleg offsite. 1-2" steel flowline from produced water tank pump to gathering system.		
Corrective Action:			Date:
Type: Compressor	# 1		

Comment:	Package compressor with 1 ton straw bales for sound wall.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Linear rod pump.		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 3			
Comment:	Wellheads with PVC bradenhead access.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	Vent stack on produced water tank.		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:	Electric driven pump on tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment. Double wall tank with electronic level controller.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 267809 Type: WELL API Number: 067-08809 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 411817 Type: WELL API Number: 067-09711 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

Facility ID: 411818 Type: WELL API Number: 067-09712 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402005457	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792274">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792274</a>
687904563	Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792265">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792265</a>
687904564	Missing sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792266">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792266</a>