

Inspection Photos  
Operator: BP America  
Location/API #: 067-05202  
Date: 4-9-2019



Photo 1. View of the project area from the northeastern corner facing center. Area around the plugged well does not appear necessary for production operations related to the producing well, and needs to be reclaimed.





Photo 2. View of the eastern project area from the northeastern corner facing southward.





Photo 3. View of what appears to be mowed annual vegetation around plugged well.





Photo 4. View of erosional channel within the eastern project area.





Photo 5. View of musk thistle (*Carduus nutans*) rosettes within the eastern project area.