

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2019

Submitted Date:

04/18/2019

Document Number:

679703766**FIELD INSPECTION FORM**Loc ID 314687 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 12930Name of Operator: CALCO DBA CALLISTER COAddress: 1230 W 1400 NCity: LEHI State: UT Zip: 84043**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Callister, Jan	801-487-4721	jec@apexoilventures.com	
Hayes, Mike	970-620-2257	hayespetro@centurytel.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229263	WELL	SI	01/15/2014	GW	103-06358	CALLISTER- GOVERNMENT 4	PR

General Comment:

Follow up inspection to FIR document 679703025 for which the corrective action of an uncapped riser is not resolved. An additional corrective action was added with this inspection.

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 801-571-5890 or 970-620-2257

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	2 uncapped risers near well head.		
Corrective Action:	Securely fasten all valves, pipes, and fillings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule.605.d.		Date: 11/30/2018

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229263 Type: WELL API Number: 103-06358 Status: SI Insp. Status: PR**Producing Well**Comment: Required reports not filed.The last reported gas production was September 2013. Gas production was observed on 10-30-2018, 2-15-2019, and 4-17-2019. The gas production is not being reported.Corrective Action: Submit reports as per Rule 206.Date: 05/20/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703767	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4799896