

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type TANK BATTERY

Comment: [Brown AG fence around tanks.](#)

Corrective Action:

Date: _____

Type SEPARATOR

Comment: [Brown AG fence around seperator, gas meter run, and ECD.](#)

Corrective Action:

Date: _____

Type WELLHEAD

Comment: [Red AG fence around wellhead.](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment

3

Comment: [Automation equipment.](#)

Corrective Action:

Date: _____

Type: VRU

1

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors

4

Comment:

Corrective Action:

Date: _____

Type: Emission Control Device

1

Comment:

Corrective Action:

Date: _____

Type: Horizontal Heated Separator

2

Comment:

Corrective Action:		Date:	
Type: Other	#		
Comment:	Bradenhead appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLs	BV CONCRETE		40.251830,-104.554330
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.251830,-104.554330
Comment:	Load lines not capped, and stained soil below load lines. see pic 3				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 05/12/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with oil tanks.			
Corrective Action:				
				Date:

Venting:

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 245369 Type: WELL API Number: 123-13164 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday April 10, 2019 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Marie D #4-10 at 123-13164 in Weld County Colorado. While there, I observed shut in well. During this inspection the following possible compliance issues were observed: Load lines not capped, and stained soil below load lines. see pic 3 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 5/12/19 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection.</p>	medinaj	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007079	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793804
685100803	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793794