

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2019

Submitted Date:

04/11/2019

Document Number:

688401815**FIELD INSPECTION FORM**

Loc ID 308821 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282649	WELL	PR	07/24/2006	GW	071-08687	APACHE CANYON 24-4	PR

General Comment:Edited 04/12/2019 to change CA date for emergency contact signage from 04/12/2019 to 05/12/2019. - C Pesicka

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/11/2019

Emergency Contact Number:			
Comment:	Sign not posted or information inaccurate at well(s) or battery	Date:	05/12/2019
Corrective Action:	Install sign to comply with Rule 210.b.		

Good Housekeeping:			
Type	TRASH		
Comment:	Door of sep/meter house; Inspector opened door to check meter and door fell on inspector hinges were not screwed in.		
Corrective Action:	Comply with 603 f	Date:	04/25/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment; 1" pipe on location		
Corrective Action:	Comply with rule 603 f	Date:	05/11/2019
Type	OTHER		
Comment:	stained soil around liquid ring riser		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	05/11/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 1		
Comment:	Liquid ring		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	HYD Skid		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	05/02/2019
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	30bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm			
Corrective Action:				
	Date:			

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 282649 Type: WELL API Number: 071-08687 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday April 11, 2019 at approximately 1311 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site AC # 24-4, at API # 05-071-08687 in Las Animas County Colorado.</p> <p>While there, I observed a production well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Equipment; Rule 603 f Corrective action date of 5-11-19 See photo 2</p> <p>Stained soil; Rule 907 A Corrective action date of 5-11-19 See photo 3</p> <p>Guy line anchor; Rule 1003 a. Corrective action date of 5-2-19 See photo 6</p> <p>Trash; rule 603 f Corrective action date of 4-25-19 see photo 1</p> <p>Location sign not posted; Rule 210 b Corrective action date of 5-11-19 See photo 1</p> <p>Emergency contact number; Rule 210 b Corrective action date of 5-12-19 (edited- C Pesicka) see photo 1</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402005783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792662
688401816	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792642