

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/12/2019

Document Number:

688401835

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
307287 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 9 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone                     | Email                        | Comment         |
|--------------------|---------------------------|------------------------------|-----------------|
| Santistevan, Vince | 719-845-2102/719-680-9705 | vincasantistevan@tcenergy.us | All Inspections |
| Beardslee, Tom     |                           | tom.beardslee@state.co.us    |                 |
| Mack, Ronald       |                           | ronaldmack@tcenergy.us       | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 217365      | WELL | PR     | 12/22/1994  | GW         | 071-06141 | APACHE CANYON 29-7 | PR          |

**General Comment:**

| Location   |   |        |                         |
|--|---|--------|-------------------------|
| Overall Good: <input checked="" type="checkbox"/>      |   |        |                         |
| <b>Signs/Marker:</b>                                   |   |        |                         |
| Type   | OTHER   |        |                         |
| Comment:   | Location  |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| Emergency Contact Number:                              |   |        |                         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date: _____             |
| <b>Good Housekeeping:</b>                              |   |        |                         |
| Type   | OTHER   |        |                         |
| Comment:   | Mechanical issue; At time of inspection it appears packing is leaking on well head. Fluid has traveled approx. 20ft of location.  |        |                         |
| Corrective Action:                                     | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. |        | Date: <u>04/13/2019</u> |
| Type   | OTHER   |        |                         |
| Comment:   | Produced water release  |        |                         |
| Corrective Action:                                     | Recover free liquids and properly dispose in accordance with 907.c.   |        | Date: <u>04/26/2019</u> |
| Overall Good: <input type="checkbox"/>                 |   |        |                         |
| <b>Spills:</b>   |   |        |                         |
| Type   | Area  | Volume |                         |
| In Containment: No _____                               |   |        |                         |
| Comment: _____   |   |        |                         |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                         |
| <b>Fencing/:</b>                                       |   |        |                         |
| Type   |   |        |                         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| <b>Equipment:</b>                                      |   |        |                         |
| Type: Ancillary equipment # 1                          |   |        | corrective date         |
| Comment:   | Electric panel  |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| <b>Venting:</b>  |   |        |                         |
| Yes/No   | NO  |        |                         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |
| <b>Flaring:</b>  |   |        |                         |
| Type   |   |        |                         |
| Comment:   |   |        |                         |
| Corrective Action:                                     |   |        | Date:                   |

**Inspected Facilities**

Facility ID: 217365 Type: WELL API Number: 071-06141 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Location is rutted and will need maintenance in the future

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

| Comment  | User    | Date       |
|--|---------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/>           On Friday April 12, 2019 at approximately 0855 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site, AC# 29-07at API# 05-071-06141 in Las Animas County Colorado.<br/>           While there, I observed a producing well site<br/>           During this inspection the following possible compliance issues were observed:<br/>           Mechanical Issue; Rule 605 d Corrective action date of 4-13-19 See photo 3<br/>           Produced water release; Rule 907 c Corrective action date of 4-26-19 See photo 3<br/>           I contacted Timber creek about leak as soon as I was able to get Phone service.<br/>           A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/>           This is a summary of inspection report.</p> | silverr | 04/12/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402007393    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794094</a> |
| 688401836    | loc pic              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794074</a> |