

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/15/2019

Document Number:

695100493**FIELD INSPECTION FORM**

Loc ID 308127 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262542	WELL	PR	11/16/2007	GW	071-07559	APACHE CANYON 26-8V	PR
268884	PIT		07/29/2003		-	APACHE CANYON 26-08V	

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	IMPACTED SOIL FANNING OUT FROM FUEL GAS SCUBBER ON COMPRESSOR OVER TO METER HOUSE APP. 5' AT ITS NARROWEST POINT (NEXT TO SCUBBER ON COMPRESSOR SKID) AND APP. 3.5' AT IS WIDEST POINT (AGAINST THE METERHOUSE). THERE IS ALSO A FILM OF OIL ON THE BOTTOM ¼ OF METERHOUSE WALL. APP. 3' BY 2' AREA OF IMPACTED SOIL ON THE NORTHEAST SIDE OF METER HOUSE.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: 05/12/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	Provide COGCC with documentaton showing approval of use of vacuum pump.		Date: 05/02/2019
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 262542 Type: WELL API Number: 071-07559 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 268884 Type: PIT API Number: - Status: Insp. Status:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 268884Lat: 37.055300Long: -104.958335Reference Point: SEOther: Length: 40Width: 30**Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: NO FREEBOARD MARKER IN PITCorrective Action: Date: 05/12/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402008421	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795133
695100494	LOCATION PHOTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795123