

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/15/2019

Document Number:

695100500**FIELD INSPECTION FORM**
 Loc ID 308125 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262539	WELL	PR	02/12/2003	GW	071-07557	APACHE CANYON 25-11V	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: THERE IS APP. 3' BY 2' AREA OF IMPACTED SOIL OUTSIDE THE NORTHWEST CORNER OF COMPRESSOR SKID.
 PHOTO 4: COMPRESSOR SKID IS FULL OF OILY WATER AND IS RUNNING OUT OF CONTAINMENT IMPACTING THE SOIL ON NORTHEAST SIDE OF COMPRESSOR SKID.

Corrective Action:

Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 05/12/2019Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Compressor

1

Comment:

Vacuum pump observed on well without COGCC approval.

Corrective Action:

Provide COGCC with documentaton showing approval of use of vacuum pump.

Date: 05/02/2019

Type: Ancillary equipment

1

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Deadman # & Marked

2

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 262539 Type: WELL API Number: 071-07557 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402008423	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795135
695100501	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795126