

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/12/2019

Submitted Date:

04/15/2019

Document Number:

695100502

FIELD INSPECTION FORM

Loc ID 307283 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217357	WELL	PR	11/29/1995	GW	071-06133	APACHE CANYON 25-4	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: IT APPEARS THAT THERE WAS AN ATTEMPT TO REMOVE SOME IMPACTED SOIL IN THE NEAR PAST AS THERE IS SOIL REMOVED FROM THE SOUTH SIDE OF COMPRESSOR SKID BUT AS SHOWN IN THIS PHOTO SOME OF THE IMPACTED SOIL WAS NOT REMOVED AND WAS COVERED UP WITH CLEAN GRAVEL.
PHOTO 4: COMPRESSOR SKID CONTAINMENT IS FULL OF OILY WATER AND IS SPILLING OVER ON LOCATION IMPACTING SOIL ON NORTHWEST CORNER OF COMPRESSOR SKID.

Corrective Action:

Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 05/12/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Compressor

1

Comment:

Vacuum pump observed on well without COGCC approval.

Corrective Action:

Provide COGCC with documentaton showing approval of use of vacuum pump.

Date: 05/02/2019

Type: Ancillary equipment

1

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217357 Type: WELL API Number: 071-06133 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402008424	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795136
695100503	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795127